

Wright Dust Feeder Spare Parts List

Replacement Parts for Wright Dust Feeder

NOTE: The WDFI is principally constructed from brass and has been obsolete for many years. The WDF-II has virtually all its parts made of stainless steel. In reading the lists below note the SS suffix indicates stainless steel construction. As the stock of brass parts is depleted, they will be eliminated from the list.

Bold part numbers are subject to direct erosive action of dust. Their lifetime cannot be predicted. These are wear components and are not subject to any warranty coverage.

Model-II (Current Model)

B2351	Cable, Controller End
DF184 SS	Container Mounting
DF183BSS	Small Dust Container
DF183SS	Large Dust Container
DF190SS	Small Cutter Blade (Incl'ds 2 screws)
DF191SS	Large Cutter Blade (Incl'ds 2 screws)
DF193	Small Cutter Head (No Blade) (Brass)
DF193C	Small Cutter Head, Carbide
DF193SS	Small Cutter Head (no blade)
DF194	Large Cutter Head (No Blade) (Brass)
DF194C	Large Cutter Head, Carbide
DF194SS	Large Cutter Head (no blade)
DF195	Split Ring (304 SS)
DF196	Sealing Washer (Neoprene)
DF197	Extension Rod
DF198C	Mini Cutter Head, Carbide
DF199	Washer .750" od x .360" id x .015" thick
DF200SS	Mini Dust Chamber
DF201	Mini Dust Packing Tool
DF202	Spigot for Pinion (Incl'd 2 of DF226)
DF226	Friction Ring (2 or 3 Required)
DF227	Small Dust Packing Tool
DF228	Large Dust Packing Tool
DF500	Sealing Disc (Neoprene)
ITEM 7	Washer .750" od x .320" id x .075" thick
ITEM 47	Nut, Hex, (5/16" BSF thread)
ITEM 48	Screw 2BA x 3/8" long thread RD/HD
ITEM 51	Washer 2BA (Small)
N301	Rubber Feet (ea)
N302	Leg Screw, Long - 4 Required
N303	Leg Screw, Short - 4 Required
N304	Motor Mount Bolts - 4 Required
N305	Drive Base Bolts - 2 Required
N306	Drive Coupling Complete
N307	Replacement Coupling Ring
N308	Right Angle Gearbox Complete w/ Mounting Plate
N309B	External Drive Gear Complete w/ 3 Mounting Screws
N310	Leg Sections

Wright Dust Feeder Spare Parts List

N316	Power Cord
SA174	Upper and Lower Pinion Assembly (Brass)
SA174 SS	Upper and Lower Pinion Assembly (Stainless)
SA176 SS	Lead Screw Spigot Assembly
SA504	Dust Outlet (Brass)
SA504 SS	Dust outlet (SS)
SA505 SS	Feed Gear & Lead Screw Assembly
V206 SS	Venturi Jet (SS)

Model-I (Obsolete Model)

DF165	Motor Spindle Collar
DF184 SS	Container Mounting
DF183BSS	Small Dust Container
DF183SS	Large Dust Container
DF189	Liner (Adapts Large Dust Container to a Small Dust Container)
DF190SS	Small Cutter Blade (Incl'ds 2 screws)
DF191SS	Large Cutter Blade (Incl'ds 2 screws)
DF193	Small Cutter Head (No Blade) (Brass)
DF193C	Small Cutter Head, Carbide
DF193SS	Small Cutter Head (no blade)
DF194	Large Cutter Head (No Blade) (Brass)
DF194C	Large Cutter Head, Carbide
DF194SS	Large Cutter Head (no blade)
DF195	Split Ring (304 SS)
DF196	Sealing Washer (Neoprene)
DF199	Washer .750" od x .360" id x .015" thick
DF202	Spigot for Pinion (Incl'd 2 of DF226)
DF208	Bevel Gear Stud
DF213	Knurled Nut
DF214	Transmission Collar
DF216	Collar
DF217	Spur Gear - 18 Teeth
DF218	Spur Gear - 36 Teeth
DF219	Spur Gear - 54 Teeth
DF220	Spur Gear - 68 Teeth
DF221	Spur Gear - 72 Teeth
DF222	Spur Gear - 76 Teeth
DF226	Friction Ring (2 or 3 Required)
DF227	Small Dust Packing Tool
DF228	Large Dust Packing Tool
DF229	Washer DF229A and DF229B - Both Needed PRICE IS FOR EACH
DF500	Sealing Disc (Neoprene)
ITEM 7	Washer .750" od x .320" id x .075" thick
ITEM 46	Nut, Hex, (2BA thread)
ITEM 47	Nut, Hex, (5/16" BSF thread)
ITEM 48	Screw 2BA x 3/8" long thread RD/HD
ITEM 49	6BA Grub Screws for DF211

Wright Dust Feeder Spare Parts List

ITEM51	Washer 2BA (Small)
ITEM68	Cirdlip Anderson - Type 1500-E303
MO1	Motor for obsolete WDF Model-I
SA174	Upper and Lower Pinion Assembly (Brass)
SA174 SS	Upper and Lower Pinion Assembly (Stainless)
SA176 SS	Lead Screw Spigot Assembly
SA504	Dust Outlet (Brass)
SA504 SS	Dust outlet (SS)
SA505 SS	Feed Gear & Lead Screw Assembly
V206 SS	Venturi Jet (SS)